

INDUSTRIAL TESTING & ANALYTICAL LABORATORIES

Regd. off.: Meher House, 6th Floor, 15, Cawasji Patel Street, Fort, Mumbai - 400 001.

Tel.: 022 - 4333 3888, 022 - 4936 9988

E-mail: inquiry@italabs.in • Web: www.italabs.in AN ISO 9001:2015 CERTIFIED ORGANISATION

TEST REPORT

Sample Submitted By Customer

Test Report No.: ITA/2025-26/080592

1. Particulars of Sample Submitted

Test Report Date

Customer Master No: C021644

Quantity Received # : 1 nos

Packing : Plastic Bag

Customer Name

: Namrata Rubber Product Pvt Ltd.

Flat No A-2, Sai Sneha Industrial Estate,

Near Shiv Temple, H.P Gas Godwon, Bhayander East,

Mira Bhayandar, Thane

401105

MH IN

: Silicone Metal Detectable

Sample Name # Letter Ref. No. #

Lt-Ref.No-NRPPL/25-26/SEP-09

Sample Receive Date: 17/9/2025

Marks #

: Silicone Metal Detectable

2. Result of Analysis: As per US FDA regulation 21-CFR-177

Parameter Name	Result	Unit	Limits
Extraction with n-hexane (after 7 hours)	14.91	mg/inch2	Not more than
Extraction with n-hexane (after 2 hours)	1.21	mg/inch2	Not more than 4
Extraction with water (after 7 hours)	1.50	mg/inch2	Not more than 20
Extraction with water (after 2 hours)	0.09	mg/inch2	Not more than 1

The sample tested is fit to be used in contact with food containing fat & also with aqueous as per US FDA regulation 21-CFR-177-2600 for rubber articles.

- END OF REPORT

Test Carried Out By :

Page 1 of 1

Chennai Branch: Lotus Court, 3rd Floor, New 338, Old 165, Thambu Chetty Street, Chennai - 600 001. | Kolkata Branch: Mercantile Building, 10, Lal Bazaar Street, Kolkata - 700 001

Collection Centres: Ahmedabad, Bangalore, New Delhi, Jaipur.



y of 3A Capital Services Ltd.

Sr.No.: M115908